

Testing Connection

Load Blink.

Upload

Check that has uploaded at bottom of window.

Don't rely on LED flashing as indicator that it worked as the programme is already loaded.

